

## CITY OF DANVILLE, VIRGINIA Utilities Department

1040 Monument St. Danville, Va. 24541 Tel (434) 799-5270 Fax (434) 799-6583

May 8, 2006

Mrs. Jessica Wilcox Service Line Inc. 2320 Zinga Drive Reedsburg, Wisconsin 53959

Re: Parts Washer Discharge

Dear Mrs. Wilcox:

I have received the analytical testing report for the discharge from one of your parts washer units. Based on this analysis and the small quantity that is discharged we do not foresee a problem with receiving this wastewater; however, anyone using this process must fill out a pretreatment questionnaire. Effluent testing must be done from the unit and included with the questionnaire. The questionnaire and analyses will determine whether a pretreatment permit will be required.

Should you have any questions on this matter, please feel free to contact me.

Sincerely,

Barry T. Dunkley, P. E., Director

Bay I ( workly

Division of Water and Wastewater Treatment

cc: Gary Manville